



FANUC CABLE BETWEEN MOXA 2150 AND CONTROL WITH SOFTWARE HANDSHAKE

RJ45 patch cable, control end mounted with a DB25M connector



FANUC CABLE BETWEEN MOXA 2150 AND CONTROL WITH HARDWARE HANDSHAKE

RJ45 patch cable, control end mounted with a DB25M connector



This cable pulls up DSR from DTR at the PC to tell the Fanuc that the CIMCO Software is running, or else the Fanuc gives Alarm 86. This requires that the "SET DTR high" checkbox in the CIMCO Software is selected.